

Delta Electric Servo press operation manual

Smarter. Greener. Together.

www.deltaww.com

Contents Delta Electric Servo press operation manual

1. Component names and functions 1-1 Component names	3
2. Basic movements and condition determination	6
2-1 Servo press basic movements	8
3. System architecture	9
3-1 Power system	10
3-2 Before powering up	10
3-2-1 Start preparations	10
3-2-2 Switches	10
3-2-3 Power up	11
3-2-4 Operation outline	11
3-2-5 Error message occurrence	12
3-2-6 I/O monitoring	12
4. System display introduction	13
4-1 Main screen introduction	14
4-2 Access	15
4-3 Shift	15
4-4 Automatic control page	16

	4-5 Recipe overview	17
	4-6 Recipe editing page	18
	4-7 Movement mode selection screen	19
	4-8 Motor operation	19
	4-9 Alarm history	20
	4-10 Manual control	20
	4-11 Load cell calibration	21
	4-12 I/O monitoring	22
5.	Movement mode introduction	24
	5-1 Position Mode	25
	5-2 Load Mode	26
	5-3 Distance Mode	27
	5-4 Load & Position Mode	28
	5-5 Load & Distance Mode	29
6.	Load cell calibration process	30
	6-1 Calibration steps	31
	6-2 Calibration example	31
7.	Recipe setting editing introduction	37
	7-1 Recipe setting steps	
8.	Error alarm report	44
	8-1 Machine alarm handling	45

1. Component names and functions

1-1 Component names4



1. Component names and functions

1-1. Component names

Standard type



Standard type body rear side



2. Basic movements and condition determination



2. Basic movements and condition determination

This section gives an overview of the servo press' s basic movements and condition determination.

The servo press offers selected operation and combined operation with several movement modes. Here we use the "position mode" to explain the principles of its movements. (Place jig on the base and punch in position. Place item to be measured on top of the jig.)

We can see that the servo press has the below primary positions:

- A. Mechanical origin position (this is the origin position for the servo press).
- B. Working origin position (this position may eliminate unnecessary movement positions).
- C. Standby position (work item's position when pressing starts on contact).
- D. End position (work item's position when pressing is done).

Except for the mechanical origin, the other three positions may all be freely determined in the recipe configurations.

The below figure illustrates the servo press' s basic movements.





2-1. Servo press basic movements

Once the start button on the user interface is pressed, the punch will rapidly drop down from the mechanical origin (A) to the working origin position at original velocity. Then it will wait until the operator presses the console buttons on the sides. When this happens, the punch will drop to the standby position at standby velocity, and to the end position at pressing velocity. When the pressing time is up, it will rise to the working origin position at original velocity. A work movement cycle is now completed.

The above movement is for position mode, configured to apply force on the work item until the specified position is reached. This is a valid mode configuration.

Besides position mode, there is load mode, for which the punch reaches the end point and changes its configuration to stop when a target load is achieved. This movement mode has the same goal as position mode, that is, to set the stop load value and apply force on the work item until the set value is reached. It is also a valid configuration mode.

Various other configuration modes (distance mode, load & position mode, etc.) are included. Please select appropriate pressing modes based on the work item' s pressing condition.

3. System architecture

3-1 Power system	10
3-2 Before powering up	10
3-2-1 Start preparations	10
3-2-2 Switches	10
3-2-3 Power up	11
3-2-4 Operation outline	11
3-2-5 Error message occurrence	12
3-2-6 I/O monitoring	12



3. System architecture

3-1. Power system

Models	dels 100kg, 300kg, 500kg, 1000kg		
Power specifications AC single-phase three-wire 220V 50/60Hz, 10A			
Models 3000kg, 5000kg			
Power specifications	AC Three-phase three-wire+ground 220V 50/60Hz, 30A		

Notes:

- 1. Be sure to ground the machine casing to ensure operator safety.
- 2. Before powering up, clear any objects or work items on the machine to prevent danger or damage to the machine.

3-2. Before powering up

3-2-1. Start preparations

Check the below before installing the power.

[Standard type]

Check if the switch on the servo press' s right side is at OFF. If at ON, switch it to OFF first.

【Unit type】

[Shared]

nsure the power cables are well connected.



Please check the voltage before turning on the power switch. Excessive voltage will cause an electric shock or machine damage.

3-2-2. Switches

Emergency switch: Shuts down the motor. If switched during running, the machine must be rebooted.

Auto/connection selection button: Toggle between standalone operation or externally controlled operation.

Start: When running, press both the left and right buttons at the same time to perform recipe movements.

No fuse breaker (NFB): Machine power switch.

3-2-3. Power up

- a. Make sure that the no fuse breaker (NFB) is positioned at ON.
- b. Reset the emergency switch (turn clockwise until it pops up).
- c. The system will now display the system standby screen (Fig. 3-2-1). Select an item from the screen to perform.

[Alarm history] : Machine alarm message history.

【I/O monitoring】: Monitor current machine IO condition.

【Initialize】: Motor repositioning.

[Manual Control] : Punch and load cell sensor test page.



Fig. 3-2-3-1

3-2-4. Operation outline

I. Under standby mode with power on:

- A. Wait for repositioning.
- B. Click on [Initialize] to reposition.
- C. Click on [Auto control] to enter the automated control page.
- D. Click on [Change recipe] to change the production recipe to be used. (Available when the auto control button is not pressed)
- E. Click on [On] to begin automated production.
- F. Use both hands to press down the left and right start buttons at the same time, and the selected recipe movement will begin.

- II. Change recipe
 - A. When auto control is not running, click directly on [Change recipe] on the auto control page to make changes.
 - B. When auto control is running, first click on [On] to return the program to standby mode, and then click on [Change recipe] to change the recipe.
- III. Modify recipe
 - A. When auto control is not running, click directly on [Home] on the auto control page to return to the homepage, and then click [Movement recipe overview] to edit and modify the recipe.
 - B. When auto control is running, click on [On] to return the program to standby mode before clicking [Home] to return to the homepage, and then click [Movement recipe overview] to edit and modify the recipe.

3-2-5. Error message occurrence

When an error message occurs, the machine will automatically enter stop mode. After fixing the issue, click [Retry] on the screen or press retry to cancel the error. If motor or load cell sensor module alarms cannot be cancelled, remove the back cover to check the motor drive' s own alarm message. Record the message and try powering off and rebooting to see if it can be cancelled. If the same problem occurs often, check the recipe configuration. If the configuration is correct, contact the manufacturer' s customer service for help.

3-2-6. I/O monitoring

Check the input or manage output based on the I/O table.



To avoid danger, keep a distance until the punch ceases movement.

4. System display introduction

4-1 Main screen introduction	14
4-2 Access	15
4-3 Shift	15
4-4 Automatic control page	16
4-5 Recipe overview	17
4-6 Recipe editing page	18
4-7 Movement mode selection screen	19
4-8 Motor operation	19
4-9 Alarm history	20
4-10 Manual control	20
4-11 Load cell calibration	21
4-12 I/O monitoring	22



4. System display introduction

Date 2018/11/08 Servo_Press A BELTA Time 09:47:53 Access: Operator Log out Morning Work order Shift: Recipe No. **Recipe Name** 1 Alarm Automatic Manual LoadCell History Calibration Control Control 10 Recipe Initialize Parameter Monitor Table

4-1. Main screen introduction

Fig. 4-1-1

Α.	Access Select machine operation access. For engineers: 1111	
В.	Shift	Click to select work shift
C.	Log out	Log out from the accessed operator status
D.	Automatic control	Click to enter the auto control screen
E.	Recipe table	Click to enter the recipe selection and editing page. Only engineers are authorized to edit recipes
F.	Alarm history	Click to view and clear machine error alarm history
G.	Initialize	Click to initiate the motor and associated machine operation parameters
н.	Manual control	Click to enter the manual motor control page
I.	Load cell calibration	Click to enter the load cell calibration page. Engineer status required for authorization
J.	I/O monitor	Enter I/O monitoring screen
К.	Parameter	Click to set the machine motor to home and to set general parameters

4-2. Access

Password insertion screen:

密碼輸入鍵	盤		\times
0	1	2	3
4	5	6	7
8	9	Α	В
С	D	E	F
CL	R	Eni	ter

4-3. Shift

Shift selection screen:

Please	choose	e shift!
Morning shift	Middle shift	Night shift
	ок	

- 1. Select the shift to be changed into
- 2. Click OK

	Automatic Control					
	Recipe					
Ple	Please put on the workpiece Buzz					
Recipe No. 0	Step: 0	Recipe Name				
Current Position (mm)	Standby Position (mm)	Pressing Position (mm)	Standby Time (s)	Total Production		
0.000	0 0.000 0.000 0.0		0.0	0		
Current Load (kgf)	Pressing Force (kgf)	Max. Load (kgf)	Pressing Time (s)	0.7		
0.000	0.000	0.000	0.0	On		
Pass NG		Measure	Production Time (s)	Curvo		
0 0		Result	0.0	Curve		
Barcode:						

4-4. Automatic control page

Fig. 4-4-1

1. Recipe	Recipe may be changed when machine is not running	12. Recipe No.	Selected work recipe
2. Home	May return to index homepage when machine is not running	13. Standby position	The recipe's preheating position
3. Buzzer off	Turn off buzzer indication	14. Recipe name	Select recipe name
4. Curve	Display load curve during measurement	15. Pressing Time	Pressing time count
5. Step	Step in target recipe movement	16. Pass	Pass count of measurements
6. Max. load	Maximum load generated by machine during the procedure	17. Pressing position	Final pressing position reached
7. Current Position	Current actual position of motor	18. Measure Result	Display measurement results
8. On	After selecting a recipe, click Start to await measurement.	19. Production time	Time required for one machine measurement
9. Barcode	Barcode number for the current production item	20. NG	NG count of measurements
10. Standby time	Time when motor reaches preheating position	21. Total Production	Total production count for the machine
11. Pressing Force	Force at final pressing	22. Current load	The actual load value

4-5. Recipe overview

k	Recipe Table Date 2018/11/08							
Rec	Recipe Number 1 Recipe Name							
Step	Pressing Mode	Upper Load Limit (kgf)	Lower Load Limit (kgf)	Upper Pos. Limit (mm)	Lower Pos. Limit (mm)	Pressing Force (kgf)	Pressing Time (s)	Standby Time (s)
1	Pressure Mode	500.000	0.000	65.000	60.000	800.000	5.0	0.5
2	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
3	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
4	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
5	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
-	公 Modify							

1.	Recipe number	Currently selected recipe number. Recipe number to be viewed may be edited
2.	Recipe name	Currently selected recipe name. Click to edit recipe name
3.	Step	Movement step for the current recipe
4.	Pressing mode	Movement mode for the current recipe step
5.	Home	Return to the previous page before entering the recipe selection page
6.	Load	Displays only when using the auto control page and Change Recipe is selected
7.	Modify	Only modifiable when entered through the main screen movement recipe overview. Select the recipe step to be modified, and then click Modify to enter the modification page.

	a F	Recipe B	Editing		Date 2018/11/08 Time 10:55:11
Recipe No.	0 Recipe N	ame		St	ep No. 1
Press Mode	Pressure Position Mode	Standby Time (s)	0.0	Load Slope Detection	OFF
Working Origin (mm)	0.000	Original Velocit y (mm/s)	0.000	Initial Upper Load Limit (kgf)	0.000
Standby Po sition (mm)	0.000	Standby Veloci ty (mm/s)	0.000	Initial Lower Load Limit (kgf)	0.000
Pressing Po sition (mm)	0.000	Pressing Veloc ity (mm/s)	0.000		
Upper Load Limit (kgf)	0.000	Lower Load Limit (kgf)	0.000		Operation
Upper Pos. Limit (mm)	0.000	Lower Pos. Limit (mm)	0.000	1	Save
Pressing Force (kgf)	0.000	Pressing Time (s)	0.0]	Return

4-6. Recipe editing page

1. Recipe number	Number of recipe in modification	13. Upper load limit	Maximum load setting that the work item may bear
2. Recipe name	Name of recipe in modification	14. Upper position limit	The work item's final upper position limit setting after pressin
3. Step No.	Number of recipe procedure in modification	15. Lower position limit	The work item's final lower position limit setting after pressing
4. Press mode	Select movement mode to change into	16. Pressing force	Target pressing force
5. Standby Time	Standby time after the motor starts and moves to standby position	17. Pressing time	Pressing and force retention time for the work item
6. Working origin	Working origin to be reached once recipe is on	18. Motor operation	Simple operation of motor movement
7. Standby position	Safe position near the work item to be reached before pressing starts	19. Save	Save the configured movement steps and recipe
8. End position	Actual position when pressing ends	20. Return	Return to movement recipe overview
9. Original velocity	Motor velocity when moving to working origin	21. Load slope detection	Choose whether to turn on load slope detection
10. Standby velocity	Motor velocity when moving to standby position	22. Initial upper load limit	Set the maximum load that the work item may initially bear
11. Pressing velocity	Pressing velocity when motor is in operation	23. Initial lower load limit	Minimum load setting that the work item may initially bear
12. Lower load limit	Minimum load setting that the work item may bear		

4-7. Movement mode selection screen



There are five pressing mode options: position, distance, load, load & position, and load & distance. Select and click OK, or click Cancel to remove selection.

4-8. Motor operation

Current Pos. :	0.000	mm
Current Load :	0.000	kgf
Load Limit :	0.000	kgf
Inch Distance:	0.000	mm
Inch Velocity :	0.000	mm/s
Jog	So Home	

1.	Current Positio	on Current position o	f the motor		
2.	Current Load	Current load as me	easured by the load cell sensor		
3.	Load Limit	When inching, the load generated is I	/hen inching, the motor cannot continue moving down if th ad generated is higher than this setting		
4.	Inch Distance	Motor inching dist	ance		
5.	Inch Velocity	Inch Velocity Motor inching or jo		city	
6.	Returnmotor to mechanical origin		8.	÷	Motor movement down
7.	JOG	Select motor jogging (JOG) or inching (INCH)	9.	1	Motor movement up

4-9. Alarm history

ANELTA	Historical error list	Date 2018/11/08 Time 11:14:08
		Clear record

Display machine' s alarm history report.

Clear records: May clear alarm history report.

Home: Return to machine homepage.

4-10. Manual control

Eigenvalues	1	mv	Ready	Zero Speed	ALM
Response time	2.5	ms	Upper limit	Home	Lower lim
Load limit	0.000	kgf			
Current Position (mm)	Current L (kqf)	oad			
0.000	0.000		Load limit	0.000	kgf
incoder : 0.00	0 m	m/s	Inching Velocity	0.000	mm/s
JOG Go Hom	e ALM	RST			↓ ↑

1.	Response time	Display current load cell module scan frequency setting					
2.	Eigenvalues	Display ei	gen values of the load	cell sens	sor currently in use		
3.	Load limit	Display cu	rrent load cell module	upper lo	oad limit setting		
4.	Current Position	Current po	osition of the motor				
5.	Current Load	Current lo	ad reading by the load	cell sen	sor		
6.	Encoder	Current ba	Current backtracking position of the motor				
7.	Load limit	When inching, the motor cannot continue moving down if the load generated is higher than this setting					
8.	Inching distance	Motor inching distance					
9.	Inching velocity	Motor inch	ning or jogging velocit	у			
Ready	Motor ready signa	al 💽	Motor movement down	BOL	Select motor jogging (JOG) or inching (INCH)		
Go Home	Return motor to mechanical origin	1	Motor movement up	ALM	Motor error alarm signal		
ALM RST	Clear motor error		Click to return to homepage	Zero Speed	Motor stop signal		
Upper limit	Motor upper limit signal	Home	Motor home signal	Lower limit	Motor lower limit signal		

4-11. Load cell calibration

	Loa	dCell Ca	alibratio	n ^r	Date 20 Time 13:	18/11/08 :03:21
	Recalibrate	x]	Current Lo (kgf)	ad C	urrent Po (mm	osition 1)
Set Points	0	(2~20)	Ready	Zero spee	d	ALM
Current Point	0	1~20 1: Zero	Upper limit	Home	Low	/er limit
STEP1:			Load limit	0.0	000	kgf
Enter Value	0.000	kat	Inch distance	0.0	000	mm
		~ 9 .	Inch velocity	0.0	000	mm/s
STEP2:	Set		Encoder :	0.0	000	mm/s
Status:	Single Finished	All Finished		o Home	ł	

1.	STEP 1: Enter value	Enter the correct load corresponding to the current calibration point				
2.	Current point	Position ur	nder calibration			
3.	Set points	Enter the n (2~20)	umber of points to be o	divided in	nto and calibrated.	
4.	Current Position	Current po	sition of the motor			
5.	Current Load	Current loa	ad reading by the load o	ell senso	or	
6.	Encoder	Current ba	cktracking position of t	he motor	r	
7.	Load limit	When inching, the motor cannot continue moving down if the load generated is higher than this setting				
8.	Inching distance	Motor inching distance				
9.	Inching velocity	Motor inching or jogging velocity				
Recalibrate	Click to start load cell calibration	÷	Motor movement down	acc	Select motor jogging (JOG) or inching (INCH)	
Bet	Click after confirming current load to save in memory	1	Motor movement up	ALM	Motor error alarm signal	
Single Finished	Displays an equals sign after completi single point calibration	ng 🖸	Click to return to homepage	Zero speed	Motor stop signal	
All Fireshod	Displays an equals sign after completi calibration	ng Go Home	Return motor to mechanical origin	Lower limit	Motor lower limit signal	

4-12. I/O monitoring

A NELTA InPut	Monitoring t	able Date 2018/11/08 Time 13:12:48
x00 Encoder OA	X20 EMS	x30 Start (external)
X01 Encoder OB	X21 Start button (right)	X31 Trig (external)
X02 Motor Ready	X22 Start button (left)	X32 ALARM RST
xo3 Upper limit	X23 Return	X33
X04 Origin limit	X24 Shutter	X34 No. 1 (external)
X05 Lower limit	X25 Switch mode	X35 No. 2 (external)
X06 Zero speed	X26 Reserved	X36 No. 3 (external)
X07 Motor Alm	X27 Reserved	X37 No. 4 (external)
		OutPut monitoring page



5. Movement mode introduction

5-1 Position Mode	25
5-2 Load Mode	26
5-3 Distance Mode	27
5-4 Load & Position Mode	28
5-5 Load & Distance Mode	29



5. Movement mode introduction

5-1. Position Mode





5-2. Load Mode

5-3. Distance Mode



5-4. Load & Position Mode



5-5. Load & Distance Mode



6. Load cell calibration process

6-1	Calibration steps	31
6-2	Calibration example	31



6. Load cell calibration process

6-1. Calibration steps

- A. Click on Access and enter engineer access code
- B. Click on Calibration to enter the page
- C. Enter 2-20 points for [Set calibration points]
- D. Click [Home] to return the motor to the mechanical origin
- E. Click [Reset] to start calibrating the load cell
- F. Ensure that there are no items pressed under the punch, and then click on [Set] to zero the load cell
- G. Once [Single Finished] lights up, start operating the motor to push down the below load cell calibration tool for measurement
- H. When the load cell calibration tool reaches a stable required load enter this value into
- I. [Step1: Enter numerical value] and click [Set]
- J. Repeat step H each time [Single Finished] lights up, until [Calibration Finished] lights up. The calibration is now done

6-2. Calibration example

A. Click on Access and enter engineer access code





- 1. Enter engineer password (Default: 1111)
- 2. Once entered, press [Enter]
- 3. If the password is correct, the below screen will be displayed.

B. Click on Calibration to enter the page



C. Enter 2-20 points for [Set calibration points]

	alibration	Date 2018/11/ Time 13:03:21	'08
Recalibrate	Current Load (kgf)	Current Position (mm)	
Set Points 0 (2~20) Current Point 0 1~20 1: Zero	Ready Zero	speed ALM	Click
STEP1:	Upper limit Ho	ome Lower lim	it
Enter Value 0.000 kgf	Inch distance	0.000 mm	n N/S
Status: Single All Finished	Encoder : JOG Go Hon		
	1	1	

The below screen will be displayed



Enter the number of points to divide into. Once entered, press [Enter].

Exp: The 1-ton model has a maximum load of 1000kg. For 5 calibration points, the load curve will be divided at 200kg intervals. The more points, the smaller intervals.

					10.00.21		
	Recalibrate	8]	Current Lo (kgf) 0.000	oad Curr	ent Position (mm) 0.000		
Set Points	0	(2~20)	Ready Zero		-20) Ready Zero sp		ALM
Current Point	0	1~20 1: Zero	Upper limit	Home	Lower limit		
STEP1:			Load limit	0.00	0 kgf		
Enter Value	0.000	kat	Inch distance	listance 0.000			
STEP2.			Inch velocity	0.00	0 mm/s		
STEP2.	Set		Encoder :	0.00	0 mm/s		
Status:	Single Finished	All Finished	Jog	o Home	+		

D. Click [Home] to return the motor to the mechanical origin

Ensure that [Encoder] and [Position] are both 0

E. Click [Reset] to start calibrating the load cell

	Recalibrat	0	Current Load (kgr)	Current F	osition n)	-CI
Set Points	0	(2~20) 1~20 1: Zero	Ready Ze	ro speed	ALM	
STEP1: Inter Value STEP2:	0.000 Set	kgt	Load limit Inch distance Inch velocity Encoder :	0.000 0.000 0.000 0.000	kgf mm mm/s mm/s	
Status:	Single	All	100 000	ome 1		
Cetta Sult Sinuletor V	Finished 234 Tenel Ver- LO3		alibration	Date 20 Time 13	× 18/11/08 23:46	
	Einished 234 Terrel Ver- LOa Calibrating	Finished READ adCell Ca	alibration	Date 20 Time 13 Current P (mr 0.0	× 118/11/08 23:46 * **********************************	
Certa Soft Sinchetor V	Finished 2.24 tend ten LO3 Calibrating 0	Finished FLAS adCell Ca (2~20)	Current Load (kgf) 0.000 Ready Ze	Date 20 Time 13 Current F (m) 0 0	× 118/11/08 23:46 *osition m) CO	
Current Point	Finished 224 tend Ver LO3 Calibrating 0 0	Finished Files adCell C: (2~20) (2~20) 1~20 1: Zero	alibration Current Load (kgf) 0.000 Ready Ze Upper limit	Date 20 Time 13 Current F (mr 0.0 ro speed Home Low	× 119/11/08 0:23:46 Position m) CO ALM ver timit	
Current Point STEP1:	Finished 224 ferrel Ver- LO3 Calibrating 0 0	Finished	Current Load (kgf) 0.000 Ready Upper limit Load limit	Date 20 Time 13 Current F (mr 0.0 ro speed Home Low	× 119/11/08 0:23:46 70silion n) 00 ALM kgf	
Current Point Cu	Finished 224 terrel Ver- LO3 Calibrating 0 0	Finished FLAS adCell Ca (2-20) (2-20) 1-20 1: Zero	Current Load (kgf) 0,000 Ready Ze Upper limit Load limit Inch distance	Dete 20 Time 13 Current F (m) 0.00 No speed Hemie Lat 0.000 0.000	× 118/11/08 23:46 70sition 10 00 ALM Ver limit kgf mm	
Current Point STEP1: Enter Value	Finished 224 tend Ver LOC Calibrating 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Finished Files adCell Ca (2~20) 1~20 1: Zero kgt	Current Load (kgi) 0.000 Ready Ze Upper limit Load limit Inch distance Inch velocity Encoder :	Date 20 Time 13 Current 1 Current 1 0.00 ro speed Hense Lev 0.000 0.000 0.000 0.000 0.000	x 118/11/08 2:23:46 Tosition m) CO ALM wer limit kgr mm/s mm/s	

F. Ensure that there are no items pressed under the punch, and then click on [Set] to zero the load cell.

G. Once [Single Finished] lights up, start operating the motor to push down the below load cell calibration tool for measurement.

	Calibrating		Current Loa (kgf) 0.000	d Curre	(mm) 0.000	
Set Points	0	(2~20)	Ready	Zero speed	ALM	
Current Point	0	1~20 1: Zero	Upper limit	Homa	Lower limit	
STEP1:			Load limit	0.000	kgt	
Enter Value	0.000	kat	Inch distance	0.000	mm (
etco:	Contractor 21		Inch velocity	0.000) mm/s	
olerz.	Set		Encoder :	0.000) mm/s	
Status:	Single	All	JOG Go	Home		

	Calibrating		Current Lo (kgf)	ad Cun	(mm)	
Set Points	0	(2~20)	Ready	Zero speed	ALM	
Current Point	0	1~20 1: Zero	Upper limit	Home	Lower limit	
STEP1:		_	Load limit	0.00	0 kgf	Click to
Enter Value	0.000	kgt	Inch distance	0.00	0 mm 0 mm/s	enter number
STEP2:	Set		Encoder :	0.00	0 mm/s	-Click
Status:	Single	All	JOG GC	Home		

H. When the load cell calibration tool reaches a stable required load, enter this value into [Step1: Enter numerical value] and click [Set].

I. Repeat steps g to h each time [Single Finished] lights up, until [All Finished] lights up. The calibration is now done.

F7	Calibrating	r	Current Lo. (kgf)	ad Cu	ment Po (mm	sition)
Set Points	0	(2~20)	Ready	Zero spee		LM
Current Point	0	1~20 1: Zero	Upper limit	Home	Low	er limit
STEP1:			Load limit	0.0	00	kgf
Enter Value	0.000	kat	Inch distance	0.0	00	mm
			Inch velocity	0.0	00	mm/
STEPZ:	Set		Encoder :	0.0	00	mm/
Status:	Single Finished	All	JOG GO	Home	I.	†

7. Recipe setting editing introduction



7. Recipe setting editing introduction

7-1. Recipe setting steps

- A. Click on Access and enter engineer access code.
- B. Click [Movement recipe overview] to enter the page.
- C. Select the [Recipe number] to modify.
- D. Select the recipe step to be modified, and then click [Modify] to enter the modification page
- E. Select a movement mode for the step: [Motionless], [Position Mode], [Load Mode], [Distance Mode], [Load & Position Mode], and [Load & Distance Mode]
- F. Select a mode and click OK, the page will display the values to be entered for that mode.
- G. Click Save when all values are entered. The screen will jump back to the movement recipe overview page.
- H. If addition of a subsequent step is required, select the next step and add it as per step d.
- I. When all steps are confirmed, click [Back] to return to home or change the recipe number to continue editing.

Note: When the first and third steps have corresponding movement modes entered but the second step does not, the recipe will stop movement once the first step ends.

Calibration example:

A. Click on Access and enter engineer access code.





- 1. Enter engineer password (Default: 1111)
- 2. Once entered, press [Enter] If the password is correct, the below screen will be displayed

B. Click [Movement recipe overview] to enter the page.



	elta Soft Simulator V2	24. Kernel Ver -	R.2.83				-	o x]
L			Rec	ipe Ta	able		Date 20 Time 10)18/11/08):35:56	
Rec	ipe Number	1		Recipe N	lame				- Click
Step	Pressing Mode	Upper Load Limit (kgf)	Lower Load Limit (kgf)	Upper Pos. Limit (mm)	Lower Pos. Limit (mm)	Pressing Force (kgf)	Pressing Time (s)	Standby Time (s)	
1	Pressure Mode	500.000	0.000	65.000	60.000	800.000	5.0	0.5	
2	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0	
3	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0	
4	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0	
5	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0	
	<u>ک</u>						M	odify	

C. Select the [Recipe number] to modify.



Enter recipe number of 0-40 to modify Once entered, press [Enter]

D. Select the recipe step to be modified, and then click [Modify] to enter the modification page

l	NELTA		Date 20 Time 10	Date 2018/11/08 Time 10:35:56				
Rec	ipe Number	1		Recipe I	Recipe Name			
Stop	Pressing Node	Upper Load Limit (kgf)	Lower Load Limit (kgf)	Upper Pos. Limit (mm)	Lower Pos. Limit (mm)	Pressing Force (kgf)	Pressing Time (s)	Standby Time (s)
1	Tessiline Mode	500.000	0.000	65.000	60,000	800.000	5.0	0,5
2	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
3	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
4	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
5	End action	0.000	0.000	0.000	0.000	0.000	0,0	0.0
	<u>2</u>						M	odify

Select the movement step to modify. The selected row will turn blue with white letters. Confirm and click [Modify]. Enter the modification page

	a F	Recipe I	Editing		Date 2018/11/0 Time 10:55:11
Recipe No.	0 Recipe N	ame		Sta	ap No. 1
Press Mode	Pressure Position Mode	Standby Time (s)	0.0	Load Slope Detection	OFF
Working Origin (mm)	0.000	Original Velocit y (mm/s)	0.000	Load Limit (kgf)	0.000
Standby Po sition (mm)	0.000	Standby Veloci ty (mm/s)	0.000	Load Limit (kgf)	0.000
Pressing Po sition (mm)	0.000	Pressing Veloc ity (mm/s)	0.000]	Motor
Upper Load Limit (kgf)	0.000	Lower Load Limit (kgf)	0.000]	Operation
Upper Pos. Limit (mm)	0.000	Lower Pos. Limit (mm)	0.000]	Save
Pressing Force (kgf)	0.000	Pressing Time (s)	0.0		Return

Displays the recipe step number

Delta Soft Simu	lator V2.24. Kernel Ver - R.1	 Recipe Ed	iting	-	–	
Recipe No.	0 Recipe N	ame		Ste	p No. 1	1
Press Mode	Pressure Position Mode	Standby Time (s)	0.0	Load Slope Detection	OFF	─── 點擊選擇
Working Origin (mm)	0.000	Original Velocit y (mm/s)	0.000	Initial Upper Load Limit (kgf)	0.000	割作供工
Standby Po sition (mm)	0.000	Standby Veloci ty (mm/s)	0.000	Initial Lower Load Limit (kgf)	0.000	
Pressing Po sition (mm)	0.000	Pressing Veloc ity (mmis)	0.000		Motor	
Upper Load Limit (kgf)	0.000	Lower Load Limit (kgf)	0.000		Operation	
Upper Pos. Limit (mm)	0.000	Lower Pos. Limit (mm)	0.000		Save	
Pressing Force (kgf)	0.000	Pressing Time (s)	0.0		Return	

E. Select a movement mode for the step:



[Motionless], [Position Mode], [Load Mode], [Distance Mode], [Load & Position Mode], [Load & Distance Mode]

Choose from five modes.

Select a mode and click [OK]. The page will automatically jump to the setup page and display the values to be entered for that mode.

Click [Cancel] to remove selection and return to the setup page.

F. Recipe step editing

Delta Soft Simu	lator V2.24. Kernel Ver - R.	2.83			- 🗆 X
	a F	Recipe I	Editing		Date 2018/11/08 Time 10:55:11
Recipe No.	0 Recipe N	ame		Ste	ap No. 1
Press Mode	Pressure Position Mode	Standby Time (s)	0.0	Load Slope Detection	OFF
Working Origin (mm)	0.000	Original Velocit y (mm/s)	0.000	Initial Upper Load Limit (kgf)	0.000
Standby Po sition (mm)	0.000	Standby Veloci ty (mm/s)	0.000	Initial Lower Load Limit (kgf)	0.000
Pressing Po sition (mm)	0.000	Pressing Veloc ity (mmis)	0.000]	Hotor
Upper Load Limit (kgf)	0.000	Lower Load Limit (kgf)	0.000		Operation
Upper Pos. Limit (mm)	0.000	Lower Pos. Limit (mm)	0.000]	Save
Pressing Force (kgf)	0.000	Pressing Time (s)	0.0		Return

Click to display the simple motor operation page, through which the punch may be moved up and down and load may be -monitored, as below figure

-Click Save when all values are entered. The screen will automatically jump back to the movement recipe overview page, as figure in step G.

0.000	mm
0.000	kgf
0.000	kgf
0.000	
0.000	mm/s
	0.000 0.000 0.000 0.000 0.000

Simple motor operation page.

G. If addition of a subsequent step is required, select the next step and add it as per step d.

A NELTA Rec			ipe Table			Date 2018/11/0 Time 10:35:56		
Recipe Number		1		Recipe Name				
top	Pressing Mode	Upper Load Limit (kgf)	Lower Load Limit (kgf)	Upper Pos. Limit (mm)	Lower Pos. Limit (mm)	Pressing Force (kgf)	Pressing Time (s)	Standby Time (s)
1	Plessure Mode	500.000	0.000	65.000	60.000	800.000	5.0	0.5
2	End action	0.000	0.000	0.000	0.000	0.000	0.0	6.0
3	End action	0.000	0.000	0,000	0.000	0.000	0.0	0.0
4	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0
5	End action	0.000	0.000	0.000	0.000	0.000	0.0	0.0

H. When all steps are confirmed, click on to return to home or change the recipe number to continue editing.

Note: When the first and third steps have corresponding movement modes entered but the second step does not, the recipe will stop movement once the first step ends.

8. Error alarm report

8-1 Machine alarm handling......45



8. Error alarm report

8-1. Machine alarm handling

Alarm code	Alarm message	Handling method	
003	Z-axis motor error alarm	Click Retry to see if the alarm can be cleared. If it cannot be cleared, check the drive alarm message and consult the below chart on how to handle.	
004	EMO (emergency off) is pressed down	Check if the emergency stop button	
005	Uninitialized _ EMO (emergency off) is pressed down	release EMO and retry.	
121	Load cell sensor module voltage error	Check if the 211LC module power source is disconnected.	
122	Load cell sensor module hardware error	Change 211LC module.	
123	Load cell sensor module CH1 input exceeds measurement range, or SEN voltage error	Check if the load cell sensor wires are loose.	
124	Load cell sensor module CH1 calibration error	Recalibrate load cell sensor.	
125	Load cell sensor module CH1 exceeds maximum load	Check if the load has exceeded the machine's upper load sensing limit	



Industrial Automation Headquarters

Delta Electronics, Inc. Taoyuan Technology Center No.18, Xinglong Rd., Taoyuan District, Taoyuan City 33068, Taiwan TEL: 886-3-362-6301 / FAX: 886-3-371-6301

Asia

Delta Electronics (Shanghai) Co., Ltd.

No.182 Minyu Rd., Pudong Shanghai, P.R.C. Post code : 201209 TEL: 86-21-6872-3988 / FAX: 86-21-6872-3996 Customer Service: 400-820-9595

Delta Electronics (Japan), Inc.

Tokyo Office Industrial Automation Sales Department 2-1-14 Shibadaimon, Minato-ku Tokyo, Japan 105-0012 TEL: 81-3-5733-1155 / FAX: 81-3-5733-1255

Delta Electronics (Korea), Inc.

Seoul Office 1511, 219, Gasan Digital 1-Ro., Geumcheon-gu, Seoul, 08501 South Korea TEL: 82-2-515-5305 / FAX: 82-2-515-5302

Delta Energy Systems (Singapore) Pte Ltd.

4 Kaki Bukit Avenue 1, #05-04, Singapore 417939 TEL: 65-6747-5155 / FAX: 65-6744-9228

Delta Electronics (India) Pvt. Ltd.

Plot No.43, Sector 35, HSIIDC Gurgaon, PIN 122001, Haryana, India TEL: 91-124-4874900 / FAX : 91-124-4874945

Delta Electronics (Thailand) PCL.

909 Soi 9, Moo 4, Bangpoo Industrial Estate (E.P.Z), Pattana 1 Rd., T.Phraksa, A.Muang, Samutprakarn 10280, Thailand TEL: 66-2709-2800 / FAX : 662-709-2827

Delta Energy Systems (Australia) Pty Ltd. Unit 20-21/45 Normanby Rd., Notting Hill Vic 3168, Australia TEL: 61-3-9543-3720

Americas

Delta Electronics (Americas) Ltd. Raleigh Office P.O. Box 12173, 5101 Davis Drive, Research Triangle Park, NC 27709, U.S.A. TEL: 1-919-767-3813 / FAX: 1-919-767-3969

Delta Greentech (Brasil) S/A

São Paulo Office Rua Itapeva, 26 – 3° Andar - Bela Vista CEP: 01332-000 – São Paulo – SP - Brasil TEL: 55-11-3530-8642 / 55-11-3530-8640

Delta Electronics International Mexico S.A. de C.V. Mexico Office

Vía Dr. Gustavo Baz No. 2160, Colonia La Loma, 54060 Tlalnepantla Estado de Mexico TEL: 52-55-2628-3015 #3050/3052

EMEA

Headquarters: Delta Electronics (Netherlands) B.V.

Sales: Sales.IA.EMEA@deltaww.com Marketing: Maketing.IA.EMEA@deltaww.com Technical Support: iatechnicalsupport@deltaww.com Customer Support: Customer-Support@deltaww.com Service: Service.IA.emea@deltaww.com TEL: +31(0)40 800 3800

BENELUX: Delta Electronics (Netherlands) B.V. De Witbogt 20, 5652 AG Eindhoven, The Netherlands

Mail: Sales.IA.Benelux@deltaww.com TEL: +31(0)40 800 3800

DACH: Delta Electronics (Netherlands) B.V. Coesterweg 45, D-59494 Soest, Germany

Mail: Sales.IA.DACH@deltaww.com TEL: +49(0)2921 987 0

France: Delta Electronics (France) S.A.

ZI du bois Challand 2, 15 rue des Pyrénées, Lisses, 91090 Evry Cedex, France Mail: Sales.IA.FR@deltaww.com TEL: +33(0)1 69 77 82 60

Iberia: Delta Electronics Solutions (Spain) S.L.U

Ctra. De Villaverde a Vallecas, 265 1º Dcha Ed. Hormigueras – P.I. de Vallecas 28031 Madrid TEL: +34(0)91 223 74 20

C/Llull, 321-329 (Edifici CINC) | 22@Barcrelona, 08019 Barcelona Mail: Sales.IA.Iberia@deltaww.com TEL: +34 93 303 00 60

Italy: Delta Electronics (Italy) S.r.l.

Ufficio di Milano Via Senigallia 18/2 20161 Milano (MI) Piazza Grazioli 18 00186 Roma Italy Mail: Sales.IA.Italy@deltaww.com TEL: +39 02 64672538

Russia: Delta Energy System LLC

Vereyskaya Plaza II, office 112 Vereyskaya str. 17 121357 Moscow Russia Mail: Sales.IA.RU@deltaww.com TEL: +7 495 644 3240

Turkey: Delta Greentech Elektronik San. Ltd. Sti. (Turkey)

Şerifali Mah. Hendem Cad. Kule Sok. No:16-A 34775 Ümraniye – İstanbul Mail: Sales.IA.Turkey@deltaww.com TEL: + 90 216 499 9910

GCC: Delta Energy Systems AG (Dubai BR)

P.O. Box 185668, Gate 7, 3rd Floor, Hamarain Centre Dubai, United Arab Emirates Mail: Sales.IA.MEA@deltaww.com TEL: +971(0)4 2690148

Egypt + North Africa: Delta Electronics

511 Cairo Business Plaza, North 90 street, New Cairo, Cairo, Egypt Mail: Sales.IA.MEA@deltaww.com

*We reserve the right to change the information in this catalogue without prior notice.